

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7

0	0	0
0	1	0
0	0	0

FIG. 8

0	$\frac{1}{6}$	0
$\frac{1}{6}$	$\frac{1}{3}$	$\frac{1}{6}$
0	$\frac{1}{6}$	0

FIG. 9

$\frac{1}{8}$	$\frac{1}{8}$	0
$\frac{1}{8}$	$\frac{1}{4}$	$\frac{1}{8}$
0	$\frac{1}{8}$	$\frac{1}{8}$

FIG. 10




FIG. 11

0	0	0
0	$\frac{1}{4}$	$\frac{1}{4}$
0	$\frac{1}{4}$	$\frac{1}{4}$

FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19

S105




FIG. 20




FIG. 21

S105




FIG. 22





FIG. 23




FIG. 24




FIG. 25

FIG. 26

0	0	0	0	0
0	0	0	0	0
1/5	1/5	1/5	1/5	1/5
0	0	0	0	0
0	0	0	0	0

FIG. 27

S105




FIG. 28





FIG. 29

FIG. 30

S105




FIG. 31




FIG. 32




FIG. 33




FIG. 34




FIG. 35




FIG. 36




FIG. 37




FIG. 38




FIG. 39




FIG. 40

0	0	0	0	0
$\frac{1}{5}$	$\frac{1}{5}$	0	0	0
0	0	$\frac{1}{5}$	0	0
0	0	0	$\frac{1}{5}$	0
0	0	0	0	$\frac{1}{5}$

FIG. 41




FIG. 42




FIG. 43

